






# TOYOTA NEW ITEMS

<p>90385-13009</p> 	<p><b>STABILIZER LINK BUSH</b></p> <p>DYNA</p> <p>00,10~02,06 XZU302,307,342            02,12~06,10 BU303,343 , WU300,340 , XZU305            02,12~08,12 WU300,340            02,12~03,12 BU300,340            06,10~11,06 WU30#,34#            17,07~ WU302,342,600,650 , XZU600,650</p>
<p>48815-60170</p> 	<p><b>STABILIZER BUSH</b></p> <p>LAND CRUISER</p> <p>99,08~01,08 HZJ78,79            99,08~08,08 FZJ78,79            99,08~07,01 HZJ78,79 , FZJ78,79 , HDJ78,79            07,01~09,07 FZJ78,79            07,01~16,08~ VDJ78,79 , HZJ78,79</p>
<p>48815-60220/60221</p> 	<p><b>REAR STABILIZER BUSH</b></p> <p>LAND CRUISER</p> <p>07,09~12,01 UZJ200 , VDJ200 , URJ200            12,03~15,08 VDJ200 , URJ202,20# , GRJ200            15,08~ VDJ200 , URJ202,20#</p>
<p>48815-60250 48815-60270/60271</p> 	<p><b>FRONT STABILIZER BUSH</b></p> <p><b>48815-60250 35Φ</b>            LAND CRUISER            07,09~12,01 VDJ200 , UZJ200 , GRJ200            11,09~15,08 URJ202,20# , GRJ200 , VDJ200            15,08~ URJ202,20# , GRJ200 , VDJ200</p> <p><b>48815-60270/60271 34Φ</b>            LAND CRUISER            15,08~ URJ200,202 , VDJ200            17,08~18,08 URJ20#            16,08~18,08 URJ200,202</p> <p>LEXUS LX450D/460/570            07,11~12,02~15,09 URJ20#            15,09~ URJ201 , VDJ201</p>
<p>90385-18021</p> 	<p><b>REAR SPRING BUSH</b></p> <p>LAND CRUISER</p> <p>99,08~01,04~07,01 HZJ71,78,79 , FZJ71,74,78,79            99,08~07,01 HDJ78            07,01~09,07 FZJ71,76,78,79 , HZJ71,76,78,79            07,01~16,08 GRJ71,76,78,79 , HZJ7# ,            VDJ76,78,79            16,08~ VDJ79,HZJ76,78,79 , GRJ7# ,            HZJ71 , VDJ76,78,79</p>